



SR#	CSI SECT	DESCRIPTION	QUANTITY	WASTAGE (10%)	QTY WITH WASTAGE	UNIT OF MEASUREMEN T	UNIT COST	TOTAL ITEM COST	TOTAL TRAD	E
										$\Box$
	DIV. 06	WOOD, PLASTIC AND COMPOSITES							\$ -	4
		Wooden Posts								
1		9'-11 1/4" Long, 3 1/2"x 5 1/4" PSL Post	1	0%	1	EA		\$ -		
2		9'-11 1/4" Long, 5 1/4"x 5 1/4" PSL Posts	4	0%	4	EA		\$ -		
3		9'-11 1/4" Long, 6"x6" Pressure Treated Posts	4	0%	4	EA		\$ -		
4		9'-11 1/4" Long, 3 1/2"x 5 1/4" PSL Posts	1	0%	1	EA		\$ -		
5		9'-11 1/4" Long, 5 1/4"x 5 1/4" PSL Posts	4	0%	4	EA		\$ -		
6		06p: 9'-11 1/4" Long, 3 1/2"x3 1/2" PSL Posts	3	0%	3	EA		\$ -		
		Structural Lumber								
7		10'-0" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	3	0%	3	EA		\$ -		
8		11'-10" Long, 2x10 SPF #2 Beams	4	0%	4	EA		\$ -		
9		12'-6" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	2	0%	2	EA		\$ -		
10		12'-8" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	6	0%	6	EA		\$ -		
11		13'-10" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	3	0%	3	EA		\$ -		
12		13'-3" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	3	0%	3	EA		\$ -		
13		14'-8" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	2	0%	2	EA		\$ -		
14		2"x6" Roof Over Hang Lumbers	17	0%	17	EA		\$ -		
15		2'-0" Long, Roof Trusses	5	0%	5	EA		\$ -		
16		21'-0" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	2	0%	2	EA		\$ -		
17		21'-5" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Beams	2	0%	2	EA		\$ -		

18	21'-5" Long,1 3/4" x 11 7/8" Laminated Veneer Lumber	2	0%	2	EA	\$	:-
19	29'-0" Long, 2"x8" Bolted Ledger	1	0%	1	EA	\$	-
20	29'-8" Long, 4"x8" Western Red Cedar Beams	1	0%	1	EA	\$	-
21	3'-5" Long,1 3/4" x 11 7/8" Laminated Veneer Lumber	6	0%	6	EA	\$	85
22	40'-10" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	2	0%	2	EA	\$	-
23	4'-2" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Beams	2	0%	2	EA	\$	NE.
24	4'-6" Long, 2x10 SPF #2 Beams	4	0%	4	EA	\$	
25	257'-4" Long, 5/4x8 Trim Board	1	0%	1	EA	\$	<u> </u>
26	6'-10" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	2	0%	2	EA	\$	
27	7'-6" Long, 1 3/4" x 11 7/8" Laminated Veneer Lumber Flush Beams	2	0%	2	EA	\$	15
	Headers						
28	1'-9" Long, 2"x8" SPF Headers	8	0%	8	EA	\$	-
29	2'-0" Long, 2"x8" SPF Headers	4	0%	4	EA	\$	-
30	2'-10" Long, 2"x7" SPF Headers	4	0%	4	EA	\$	-
31	2'-10" Long, 2"x8" SPF Headers	4	0%	4	EA	\$	-
32	2'-11" Long, 2"x8" SPF Headers	6	0%	6	EA	\$	-
33	2'-3" Long, 2"x8" SPF Headers	2	0%	2	EA	\$	·=
34	2'-6" Long, 2"x8" SPF Headers	12	0%	12	EA	\$	S-2
35	2'-7" Long, 2"x8" SPF Headers	8	0%	8	EA	\$	
36	2'-8" Long, 2"x8" SPF Headers	4	0%	4	EA	\$	-
37	2'-9" Long, 2"x8" SPF Headers	6	0%	6	EA	\$	<b>∴</b>
38	3'-10" Long, 2"x8" SPF Headers	2	0%	2	EA	\$	-
39	3'-3" Long, 2"x8" SPF Headers	8	0%	8	EA	\$	12
40	4'-3" Long, 2"x8" SPF Headers	8	0%	8	EA	\$	-
41	4'-8" Long, 2"x7" SPF Headers	2	0%	2	EA	\$	-
	5'-0" Long, 2"x7" SPF Headers	2	0%	2	EA	\$	-
42		2	0%	2	EA	\$	115
	5'-0" Long, 2"x8" SPF Headers	_				920	
42	5'-0" Long, 2"x8" SPF Headers 5'-3" Long, 2"x7" SPF Headers	2	0%	2	EA	\$	
42 43		2	0% 0%	2	EA EA	\$ \$	-

47	11! /" Long 11 7/0" TIL Wood loists	2	00/	2	ΕΛ	ċ	
	11'-4" Long, 11 7/8" TJI Wood Joists	2	0%	2	EA	\$ ^	
48	13'-0" Long Girder Trusses	2	0%	2	EA	\$ ¢	-
49	13'-0" Long, Roof Trusses	22	0%	22	EA	\$	
50	13'-6" Long, 2"x8" Rafters	6	0%	6	EA	\$ \$	-
51	14'-0" Long, Roof Trusses	23	0%	23	EA	\$	-
52	14'-8" Long, Roof Trusses	22	0%	22	EA	\$	87
53	15'-10" Long, 11 7/8" TJI Wood Joists	10	0%	10	EA	\$	_
54	17'-0" Long, Roof Trusses	16	0%	16	EA	\$	-
55	19'-10" Long, 11 7/8" TJI Wood Joists	41	0%	41	EA	\$	12
56	21'-5" Long, 11 7/8" TJI Wood Joists	26	0%	26	EA	\$	-
57	24'-11" Long Girder Truss	1	0%	1	EA	\$	-
58	26'-0" Long, Roof Trusses	11	0%	11	EA	\$	-
59	26'-9" Long, Roof Trusses	4	0%	4	EA	\$	0. <del>1</del>
60	3'-10" Long, 11 7/8" TJI Wood Joists	1	0%	1	EA	\$	-
61	40'-10" Long Girder Trusses	2	0%	2	EA	\$	-
62	41'-3" Long, Roof Trusses	8	0%	8	EA	\$	-
63	41'-3" Long Girder Truss	1	0%	1	EA	\$	-
64	4'-4" Long, Roof Trusses	9	0%	9	EA	\$	87
65	8'-6" Long, 9 1/2" TJI Joists	3	0%	3	EA	\$	-
66	7'-2" Long Girder Trusses	2	0%	2	EA	\$	-
67	9'-6" Long Girder Truss	1	0%	1	EA	\$	-
	Wall Studs						
68	2"x4" Wood Studs	2,829	10%	3,112	LF	\$	-
69	2"x6" Wood Studs	3,268	10%	3,595	LF	\$	88
	Top and Bottom Plates						
70	2"x4" Top Plates	439	10%	483	LF	\$	-
71	2"x4" Bottom Plates	439	10%	483	LF	\$	-
72	2"x6" Top Plates	497	10%	547	LF	\$	-
73	2"x6" Bottom Plates	209	10%	230	LF	\$	-
74	2"x6" Mudsill	288	10%	316	LF	\$	: <del>-</del>
		7					
	Plywood Sheathing						
75	3/4" Plywood Floor Sheathing (132 Sheets of 4'x8')	<b>⊿</b> 3,842	10%	4,226	SF	\$	-
75 76		3,842 3,864	10% 10%	4,226 4,250	SF SF	\$ \$	-

SUB T	OTAL		\$ -	\$ :-
OVER	HEAD & PROFIT (25%)	25%	\$ u <del>.</del>	\$ -
TOTA	L BID		\$ -	\$ -